

Wireline Entry Guide (WEG)

The UMS Flowell Wireline Entry Guide (WEG) is made up to the bottom of the last joint of bypass tubing below the ESP. The WEG ensures a smooth and guided re-entry of the wireline or coil tubing tool strings back into the bypass tubing after completion of logging or well intervention.

The smooth edges prevent cutting of wireline or slickline cable during logging operations.

FEATURES & BENEFITS

- Full mule shoe design
- Smooth internal corners
- Finned features for centralization
- Compact design
- Precision investment casting

SPECIFICATIONS

- Low alloy steel or 13Cr material options
- 3.8" OD to fit inside 4-1/2" liner



Technical Specifications - Wireline Entry Guide

Part Number	Box Thread	Outside Diameter (in)
WEG-00002	2-7/8" 6.4# F2J	3.80
WEG-00004	2-3/8" 4.6# F2J	3.80
WEG-00005	2-1/8" 2.4# F2J	3.80
WEG-00008*	2-7/8" 6.4# F2J	3.13
WEG-00011	4-1/4" 10# F2J	4.83
WEG-00012	2-7/8" 6.4# F2JLB	3.80
WEG-00013	2-3/4" 4.4# F2J	3.80
WEG-00015	2-1/8" 2.4# F2J	2.13 (54mm)

* Plain Re-Entry Guide

